



Model: PS-W000-3S

-Insertion Loss



-Return Loss



-Isolation



-Phase Error

